



Selected Project Reference List

Asbestos Identification, Monitoring and Removal Projects

HSP has completed various projects involving the identification and monitoring of asbestos containing products used in construction. Numerous industrial and commercial demolition or modification projects have also been completed and/or supervised where asbestos containing materials have been removed. Several projects are outlined below.

Asbestos Survey

Pulp and Paper Mill, Central Canada

A plant wide survey was completed to identify all asbestos containing materials, including piping and equipment insulation, ceiling and floor tiles, sprayed on fireproofing and insulation, etc., in a large pulp and paper complex. In cases where asbestos was suspected, its presence was confirmed by sampling and analyses.

All areas surveyed were identified and appropriately labelled as whether containing or not containing asbestos. The survey was the initial phase of a systematic mill wide program to eliminate asbestos.

Phase 1 and 2 Environmental Site Assessments

Numerous Industrial and Commercial Properties, throughout Canada

Numerous Phase 1 and Phase 2 environmental site assessments have been completed on industrial and commercial properties to identify potential environmental liabilities prior to undergoing real estate transactions. Part of the assessment involves an inspection of the building and construction materials. Potential asbestos containing materials (insulation, floor and ceiling tiles, etc.) are identified and sampled, if necessary, for analysis.



Selected Project Reference List

Asbestos Identification, Monitoring and Removal Projects (Cont'd)

Airborne Asbestos Monitoring Commercial Building (Bank), Central Canada

Airborne asbestos concentrations were monitored in the workplace air in a commercial building known to contain asbestos building materials. Results were evaluated and compared with exposure limits prescribed by the Ontario Occupational Health and Safety Act and regulations.

Asbestos Removal Ontario Government Tourist Office, Central Canada

The removal of asbestos containing building materials following procedures prescribed by the Ontario Occupational Health and Safety Act and regulations during demolition of an Ontario Tourist Office was coordinated and supervised.