



## Selected Project Reference List

### Environmental Compliance Audits, Phase 1 and 2 Site Assessments, Decommissioning and Remediation

*HSP has completed environmental audits and Phase 1 and 2 Site Assessments on industrial, commercial, residential and agricultural sites. Detailed site investigations, site remediation, and monitoring programs, conducted in accordance with environmental legislation and cleanup guidelines have also been completed. Site remediation projects have included the removal of underground tanks, PCB contaminated transformers, asbestos, lead/hydrocarbon contaminated soils and underwater sediments laden with metals PCB's and nutrients.*

Underground Fuel Oil Tank Removal and Remediation	Morrisburg, Ontario
Phase 1 & Phase 2 Environment Site Assessment - Custom Woodworking and Fine Furniture Manufacturing and Finishing Facility	Long Sault, Ontario
Printing Plant Phase 2 Investigation, Decommissioning and Site Remediation	Cornwall, Ontario
Phase 1 Environmental Site Assessment - Consumer Products Manufacturing Facility	Morrisburg, Ontario
Phase 1 and Phase 2 Environmental Site Assessment and Remediation - Warehouse (previous fibreglassing operation)	Morrisburg, Ontario
Phase 1 Environmental Site Assessment - Commercial Office Property	Cornwall, Ontario
Phase 1 Environmental Site Assessment - Metal Products Manufacturing Plant (previous printing company)	Eastern Ontario
Phase 1 Environmental Site Assessment - Autobody Shop	Eastern Ontario
Phase 2 Environmental Site Assessment - Commercial Strip Mall and Office Complex (previous dry cleaning facility)	London, Ontario
Phase 1 and 2 Environmental Site Assessment - Hotel and Gas Bar	Cornwall, Ontario
Phase 1 Environmental Site Assessment - Auto Repair Shop	Eastern Ontario
Phase 1 and 2 Environmental Audit, Construction Company	Gananoque, Ontario
Underground Storage Tank Investigation - Ministry of Transportation	Southwestern Ontario
Site Remediation - Industrial Discharge (metals, oil and grease)	Cornwall, Ontario
Printing Plant - Liquid, Air and Solid Waste Release Point Study	Cornwall, Ontario
Phase 1 Environmental Site Assessment - Commercial Mall	London, Ontario
Phase 1 Environmental Site Assessment - Training Institute	Morrisburg, Ontario
Phase 1 Environmental Site Assessment - Industrial Facility	Long Sault, Ontario
Site Remediation - Private Automotive Repair Garage	Cornwall, Ontario
Environmental Waste Audit / Decommissioning - concrete R & D Facility	Woodstock, Ontario
Contaminated Sediment Assessment and Removal	Collingwood, Ontario